Storage of compressed fibre gasket materials - DIMERSIL

Recommended conditions:

1. dry and dark warehouse
2. storage temperature: –10 do +25°C, the sheets get harder at temperatures higher to +30 °C
3. relative humidity: 50 - 60%
4. do not stock close to heat sources (radiators, heating pipe, resources heat transmission etc.)
5. avoid direct sunshine (UV radiation can be crisp up of sheets)
6. stock on the flat and clear foundation in original package

Recommended storage life:

2 years, depending above mentioned conditions

DIMER, spol. s r. o.
Zelená 505, 760 01, Zlín-Kudlov
Czech Republic
www.dimer.cz

Technical Support
GSM: +420 732 262 243
E-mail: tech.support@dimer.cz

version: GC1-1-2-2015

All information in this document is good faith and no warranty is given or implied since in the application and use is beyond our control.