Storage of semimetallic gaskets - DIMERFLEX

Recommended conditions:

1. dry and dark warehouse
2. relative humidity: 50 - 60%
3. storage temperature: –20 do +40°C
4. stock on the flat and clear foundation in original package
5. use caution for manipulation, avoid damage to the sealing element
6. do not burden other objects

Recommended storage life:

no limited, depending on the above mentioned conditions

DIMER, spol. s r. o.
Zelená 505, 760 01, Zlín-Kudlov
Czech Republic
www.dimer.cz

Technical Support
GSM: +420 732 262 243
E-mail: tech.support@dimer.cz

version: GS1-1-2-2015

All information in this document is good faith and no warranty is given or implied since in the application and use is beyond our control.